

FOTECHEM 2001

Hazard-free, flow-support coupled up with degreaser for direct emulsion coating.

Combined degreaser and wetting agent that prepares mesh for stencil making.

1. DESCRIPTION

- ◆ Ready-to-use gel wetting agent and degreaser.
- ◆ Can be used with any emulsion or capillary film.
- ◆ Contains powerful degreasers for cleaning, combined with wetting agents to improve stencil adhesion.
- ◆ Specially recommended to maximize adhesion & improve exposure latitude of one-part photopolymer stencil products.
- ◆ Can be used with synthetic monofilament and stainless steel mesh.

2. DIRECTIONS FOR USE

For new stainless steel mesh or for previously abraded synthetic monofilament mesh, apply Fotechem 2001 liberally to both sides of wet or dry screen with a brush or sponge. Rinse the screen with a strong water spray to remove all traces of Fotechem 2001. Dry the clean freshly prepared screens and use immediately or store in a dust-free environment.

3. PACKAGING

Available in 1, 5 and 50 gallon containers.

4. HEALTH & SAFETY

- ◆ For industrial use only, keep away from children
- ◆ For eye protection wear safety glasses
- ◆ A Safety Data Sheet is available on request

5. STORING

- ◆ 1 year

Dynamesh

These Technical Informations are published without warranty. The results shown in these Technical Informations are based on laboratory testing. The supplier declines any responsibility for incorrect use of these products which are manufactured and sold for industrial use only.